



**WRIGHT STATE UNIVERSITY**  
 Engineering & Construction Department  
 (937) 775-2587 - [construction@wright.edu](mailto:construction@wright.edu)

**WSU MONUMENT LOCATIONS**

OUPS must be contacted and a WSU Dig Permit must be filed out at least three business days before you begin work. Contact WSU for more information.

BY D. KENDRICK	SCALE nts	DATE 8/18/2010
-------------------	--------------	-------------------

**GROUND CONTROL COORDINATE LISTING**  
**Wright State University**  
**Geodetic Control and Orthophotography Project**  
**Location: Wright State University Campus, Fairborn, Ohio**  
**Horizontal Datum: NAD 83 (1995)**  
**Vertical Datum: NAVD 88**  
**Units: US Survey Feet**  
**State Plane Zone: Ohio South**  
**Geoid Model: Geoid 03**  
**Coordinate System: Grid**

**New 2005 Photo Control Stations:**

Station Name	Grid Northing (US FT)	Grid Easting (US FT)	Station Elevation (US FT)
P1	657406.72	1526397.22	831.31
P2	655924.98	1529923.00	839.21
P3	657440.45	1531493.68	819.15
P4	657592.67	1534875.38	842.92
P5	656146.29	1526647.15	835.90
P6	655818.39	1530816.73	833.17
P7 (WSU 101A)	655268.05	1532203.65	840.90
P8	655413.77	1534621.40	839.73
P9	653822.03	1534900.16	863.90
P10 (WSU 102A)	653420.30	1533232.24	878.07
P11 (WSU 104A)	653767.71	1529290.52	937.90
P12 (WSU 105)	654416.08	1527489.10	937.85
P13	651826.96	1526742.53	985.74
P14 (WSU 103A)	652383.83	1529857.34	935.73
P15 (WSU 102)	652436.89	1532711.13	900.98
P16	651990.89	1535028.82	915.47
P17	651120.90	1535027.57	924.79
P18	650898.22	1532865.88	936.02
P19 (WSU 103)	651473.37	1530164.84	933.72
P20	650305.20	1526334.51	992.76
WSU 101	655115.14	1533162.54	848.13
WSU 103B	651286.75	1529228.93	942.86
WSU 104	653234.57	1527977.70	956.41
WSU 105A	655076.04	1528262.27	912.50